


Deficiències constructives-estructurals

ADREÇA	Estructura	DC. Coberta	DC. façana	DC. pati	SUBTOTAL
1 Ctra de Barcelona 306		31.030,00 €	95.437,58 €		126.467,58 €
2 C Paris 19		27.384,79 €		12.579,27 €	39.964,06 €
3 Ctra de Barcelona 340					
4 Via Sant Oleguer 52					
5 C Onze de Setembre 2-10					
6 Via Sant Oleguer 53		14.966,45 €		34.059,54 €	49.025,99 €
7 C Ausias March 12					
8 Rda Santa Maria 277					
9 Via Sant Oleguer 10-12		67.077,62 €			67.077,62 €
10 Rda Santa Maria 279		3.167,20 €			3.167,20 €
11 Via Sant Oleguer 41-45			76.622,70 €		76.622,70 €
12 C Ausias March 2			39.007,59 €		39.007,59 €
13 C Ausias March 4			38.113,31 €		38.113,31 €
14 C Galcerán de Pinós 5-9			21.294,27 €		21.294,27 €
15 Via Sant Oleguer 57		35.932,88 €			35.932,88 €
16 Via Sant Oleguer, 21			13.465,13 €		13.465,13 €
17 Via Sant Oleguer, 23			13.465,13 €		13.465,13 €
18 C Ausias March, 7			25.547,06 €		25.547,06 €
19 Via Sant Oleguer, 17-19			23.254,30 €		23.254,30 €
20 Rda Santa Maria 271					
21 C Ramon Muntaner 38	75.326,83 €		71.831,96 €	8.712,26 €	155.871,05 €
22 C Ausias March 33	35.337,17 €		12.356,96 €		47.694,13 €
23 Via Sant Oleguer 31				51.498,29 €	51.498,29 €
24 Rda Sta Maria 273			9.576,00 €		9.576,00 €
25 C Galceran de Pinós 11			6.705,28 €		6.705,28 €
26 C Saboneria 9	11.458,29 €	12.462,76 €	4.870,45 €		28.791,50 €
27 C Ramon Muntaner 6					
TOTAL PRESSUPOST	122.122,29 €	192.021,70 €	451.547,72 €	106.849,36 €	872.541,07 €



DEFICIÈNCIES CONSTRUCTIVES-ESTRUCTURALS

Rehabilitació 27 d'edificis: Pla de Barris La Romànica